






2. solder
3. signal1
4. outline
5. componentmask
6. soldermask
7. plated-drill
8. topsilk
9. bottomsilk
10. topassembly
11. bottomassembly
12. fab



























There are 2 different drill sizes used in this layout, 285 holes total

Symbol Diam. (Inch) Count Plated?


Y 0.030 283 YES

+ 0.080 2 YES

Title: (unknown) - Fabrication Drawing

Author: Oliver Lehmann

Date: Fri Aug 21 17:57:59 2009 UTC



Board outline is the center-line of this path